Power Regenics

GE MK V TCPSG Power Supply Refurbishment Program

This picture is from an operating MK V Power Supply.

If the resistors on your Power Supplies look like this

Then the unit will likely fail in operation

Operational failure results in expensive damage to other cards




Powergenics offers a preventative solution to extend the life of TCPSG power supplies!

After evaluating over 100 previous repairs, Powergenics recommends a 16 component upgrade

These new components are higher quality and ensure longer life.

Refurbishment turnaround is 2 weeks with **two year warranty**



Contact us for your quote today! 800-861-9773 or rriggs@powergenics.com